Michael O. Leavitt Governor Ted Stewart Executive Director

Executive Director
Robert L. Morgan
State Engineer
P.O. Box 718
Price, Utah 84
801-637-1303

Southeastern Area 453 South Carbon Avenue P.O. Box 718 Price, Utah 84501-0718

June 3, 1993

015/032 #2 CC J. Smith

BECERVED

JUN 0 7 1993

DIVISION OF

Division of Oil, Gas & Mining Attn: Daron Haddock 355 West North Temple 3 Triad Center Suite 350 Salt Lake City, Utah 84180-1203

Re: Permit Renewal Application

Genwal Coal Company - Crandall Canyon Mine

Dear Daron:

The above referenced mine plan has been reviewed. At this time, there are not any issues requiring further permitting or processing from this office. However, I do offer the following comments:

- 1. Reference was made in several sections of the plan regarding the development of alternate water supplies in the event that mining activities impact a water source. Should mitigation be required, any proposals should be coordinated with this office.
- 2. Page 7-43 identifies a study by which an unnamed drainage in Blind Canyon will be monitored to determine effects of retreat mining produced subsidence on watershed erosion. Information relating to the finding of this study would be appreciated.

I apologize for the delay in returning my comments to you. Should you have any questions, please feel free to contact me.

Sincerely,

William A. Warmack

Assistant Regional Engineer

cc: Genwal Coal Company

Attn: Larry W. Johnson

William A. Marmack

P.O. Box 1201

Huntington, Utah 84528

WAW/mjk

